

Schemenübersicht









Schémas généraux





Schemi elettrici



Electro Mica AG

8753 Mollis

unbeleuchtet non lumineux non illuminato	Orientierungsbeleuchtung éclairage d'orientation illuminazione d'orientamento	Kontrollbeleuchtung éclairage de contrôle illuminazione di controllo	Dauerbeleuchtung éclairage permanent luce continua
 <p>SCHEMA 1 (3+3) Max. 1.5 mm²</p>	<p>Orientierungsbeleuchtung siehe Schema 3</p>	<p>Kontrollbeleuchtung siehe Schema 3</p>	<p>Dauerlicht siehe Schema 3</p>
 <p>SCHEMA 3 Max. 1.5 mm²</p>	 <p>SCHEMA 3 Orientierung Max. 1.5 mm²</p>	 <p>SCHEMA 3 Kontrollleuchte Max. 1.5 mm²</p>	 <p>SCHEMA 3 Dauerlicht Max. 1.5 mm²</p>
 <p>SCHEMA 6 Max. 1.5 mm²</p>			
 <p>Taster Max. 1.5mm²</p>			 <p>Taster Dauerlicht Max. 1.5mm²</p>

 <p>KK SCHEMA 1 (3+3) Max. 1.5 mm²</p> <p>The diagram shows a 3-phase supply (L, N, PE) connected to a 3-phase motor. Two phase conductors are connected to two light bulbs (represented by circles with an 'X'). The motor is connected to all three phase conductors.</p>	<p>Orientierungsbeleuchtung siehe Schema 3</p>	<p>Kontrollbeleuchtung siehe Schema 3</p>	<p>Dauerlicht siehe Schema 3</p>
 <p>KK SCHEMA 3 Max. 1.5 mm²</p> <p>The diagram shows a 3-phase supply (L, N, PE) connected to a 3-phase motor. One phase conductor is connected to a light bulb. The motor is connected to all three phase conductors.</p>	<p>Orientierungsbeleuchtung siehe Schema 3</p>	<p>Kontrollbeleuchtung siehe Schema 3</p>	<p>Dauerlicht siehe Schema 3</p>
 <p>KK SCHEMA 6 Max. 1.5 mm²</p> <p>The diagram shows a 3-phase supply (L, N, PE) connected to a 3-phase motor. The motor is connected to all three phase conductors. There are additional connections to the motor's control terminals, but no lighting is shown.</p>			
 <p>KK Taster Max. 1.5mm²</p> <p>The diagram shows a 3-phase supply (L, N, PE) connected to a 3-phase motor. One phase conductor is connected to a light bulb (represented by a circle with an 'L'). The motor is connected to all three phase conductors.</p>			<p>Dauerbeleuchtung sieheTaster</p>